



Notes:

Torque Specifications:

- a. Connector: TNC - 8 N·m (72 in·lb),
type-N - 11 N·m (100 in·lb)
- b. Base Mount: M18X1 Nuts - 14 N·m (125 in·lb)

Instructions to prevent self-loosening of the M18X1 nuts:

Step 1: Tighten first M18X1 nut to 6 N·m (53 in·lb).

Step 2: Install second M18X1 nut then use a spanner
to hold the first nut stationary.

Step 3: Tighten second M18X1 nut to 14 N·m (125 in·lb).

Alternatively: Use one M18X1 nut and a lock washer.